

# **Accessibility Plan**

September 2022

#### This document should be read in conjunction with the School's SEND Policy

This policy sets out the proposals of the school to increase access to education for disabled students in the three areas required by the planning duties in the Disability Discrimination Act 2002 and the Equality Act 2010:

- increasing the extent to which disabled students can participate in the school curriculum;
- improving the environment of the school to increase the extent to which disabled students can take advantage of education and associated services;
- improving the delivery to disabled students of information which is provided in writing for students who are not disabled.

Rugby School is an academically selective school and it is our aim to ensure that any prospective student, who fulfils Rugby School's admissions requirements, is able to come to the school irrespective of personal disability or special educational need.

Our core values are built around providing a secure, collaborative and purposeful learning culture, and whilst we have collective aims, everyone is treated as an individual. We are therefore equally ambitious for our disabled students and staff.

#### 1. Access to the curriculum

Students with identified or suspected specific learning difficulties are supported by our Learning Development department. Rugby School's SEND Policy can be downloaded from the website.

The school has had an Accessibility plan since 2003 and since that date the following steps have been taken to improve the accessibility of disabled students to the curriculum:

- The parents of all prospective students with special educational needs, including medical or physical disabilities are encouraged to discuss their needs prior to our entrance procedures to enable us to make any adjustments that may be required;
- Students in the lower school with SEND may opt to receive learning support lessons within the curriculum at no extra cost;
- Students in the Upper School may receive support lessons at no extra cost during a study period according to need. Staff receive on-going training to enable them to understand the needs of SEND and disability including deaf awareness training;
- Individual support sheets are prepared to inform teaching staff about the strengths and weaknesses of SEND/disabled students and to offer specific guidance on appropriate adjustments and strategies for teaching;
- Creation of dedicated learning support centre to facilitate easier access to resources for staff and students;
- ICT resources have been introduced to screen for SEND in all new students to the school;

In the three year period from 2020-2023, the following developments are planned to increase access to the curriculum:

- All pupils with a disability will be observed by LD staff when sitting key internal examinations to ensure that their needs are understood and accommodated through exam access arrangements.
- More streamlined systems of reporting will be developed to enhance monitoring.
- Autism awareness sessions will be delivered to all new FB pupils during their first term.

All students are welcomed into our sports, games and extra-curricular programmes, with special attention paid and allowance made to any who have any form of disability.

#### 2. Physical Access

Rugby is committed to improving accessibility to our buildings wherever it can. A full accessibility audit of every building has been conducted from which a programme of work has been established and is controlled by the Estate Manager. Much progress has already been made and a full summary of the building audits, the work identified, and the work completed to date is contained at appendix 1.

An historic estate such as ours poses many challenges to adaptation and accessibility but none the less very many alterations have been completed to the physical environment all with the aim of adapting and making accessible as many areas as possible across the campus. It should however be noted that it may not be possible to make all areas accessible given Planning Authority and budgetary limits.

All new buildings, such as Modern Languages, the new boarding house and the new day complex are of course fully compliant with the latest Building Regulations. Where we are completely refurbishing existing buildings, every effort is made to make the building as compliant as possible. Examples of this include The Music School and Science School which now have level access, disabled toilet facilities and lifts to give access to all floors following their refurbishment.

In addition to major project work the School is committed to adapting as many buildings as possible and with this in mind the Estates Department control a substantial annual budget specifically designed to fund other priority access projects. This has allowed for the construction of ramps (Bookshop, Bursary, History and Macready Theatre) the installation of lifts (Sport Centre, Design Centre and Macready Theatre) and for other programmes such as providing designated and signed disabled parking across the Estate, provision of hearing loops and for adapting and providing handrails along with many other improvements. The Building Audits provide a clear prioritised programme of work to ensure the School is constantly improving its provision.

Improving the accessibility of the public buildings has been a primary concern. Works completed here include providing ramped access to the Bookshop, Bursary and Macready Theatre, providing disabled toilet facilities at the Temple Speech Room and Music School and providing automatic doors at the Sport Centre. After lengthy planning negotiations, a ramp was provided to another of our most historic buildings, the Temple Reading Room, the ramp also serves the History Department. After challenging planning negotiations, alterations were agreed and have been implemented to the historic Macready Theatre which will transform its accessibility and secure its future use for the wider community as well as for the school. Improvements to the theatre include a new external ramp and a lift to auditorium level with access to disabled seating.

In February 2019 the construction of a new fully accessible boarding house was completed (New House.) With regard to the existing Boarding Houses, A £3.6m upgrade to Sheriff house completed in September 2020, this boys house is now fully accessible. Whitelaw House is currently under refurbishment and will be fully compliant on completion in 2023. Separately an additional girls and a boy's house have been identified as most suitable for adaptation (Griffin and Michell,) and level access to the buildings has already been provided – At Michell a fully compliant bedroom with bathroom facilities has been installed along with a number of internal ramps and other alterations as part of its major house refurbishment. Elsewhere further adaptions would need to be made on a case-by-case basis should a student with such needs present, but by having addressed the major physical obstacle to access in these houses and in the new boarding house the School is as prepared as it can be in advance. The recently completed extension to the boy's and girl's day house provides fully compliant accommodation for day pupils.

The dedicated annual budget for physical adaptions is £25,000 and is managed by The Estate Director, Judith Robinson. In addition, the School regularly supports this with additional funds from the wider capital plan to achieve larger projects. The attached Building Audit identifies the planned and completed works in the current plan period.

# 3. Improving the delivery to disabled people of information that is provided in writing for people who are not disabled

All written communication, either hard copy or electronic, can be provided on request in a suitable format to enable access. This includes large print and audio formats. A video link has been provided for parents at meetings if access has not been gained readily.

Authorised Compliance Committee:	
Date:	23 September 2022
Authorised Little Grange Director	
Date	



# Building Access Audit and Accessibility Plan

This document was originally produced in 2002 and has been bi annually updated since then to reflect the progress made in adapting the School's physical environment.

The section coloured white indicates work still to be done

The section coloured blue indicates work that has been completed

The section coloured peach indicates items not applicable e.g. No lift required because it is a single story building.

The annual budget (£25,000 in (2022/23) is used to address items in the 'Priority 1-3 years' column. Priority 1 items will be addressed first. Feasibility 1-10 ranks items by feasibility with 1 as most possible. The current 3 year plan period runs from 2020 – 2023.

This document is updated annually to reflect progress made.

# Art & Design Centre

The accommodation is located over two floors accessed on the ground through a T-shaped corridor. This is served by three entrances, two ramped from "The Close", and a third from the Science school at first floor level. Two staircases give access to the first floor internally at either end of the corridor. A third small stair gives access to the Media Centre on the lower ground level. There is a disabled toilet at ground level. Limited parking is provided for this building.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
	,	,	1 - 3 Years	3 - Onwards	1-10
Work Required:					
Completed:					
Access to all floors above ground	Lift to all floors				
Lifts	Lift installed	Not to top floor of Lewis Gallery		-	
Visual fire alarm adaption	Compliant adaption complete	N/A			
Door Furniture	Replaced with Compliant design				
Not Required:	_				
Toilets & washing facilities	Disabled toilet on ground floor	N/A			
Door Vision Panels	Compliant	N/A			
External hard landscaping	Acceptable	N/A			

	tadit 2022			
1	Other	Limited car parking available inc designated		
		parking space		
		Installed 2020		
	Door Entry System			

# Bookshop

The accommodation is located on the east side of the Close, adjacent to the perimeter path/service road. The entrance is via three steps on the Northerly elevation. The accommodation is on one level. The sales area is an open plan space and to the right of the sales desk is a disabled toilet.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
	,	·	1 - 3 Years	3 - Onwards	1-10
Work Required:					
Door furniture	Unsuitable	Modify as appropriate	<b>~</b>		3
Completed:					
Access to all floors	Ramp installed				
Handrails	Installed				
Entrances and exits inc emergency use	Access/exit possible with assistance	Ramp installed			
Furniture	Counter adapted				
Other	Designated parking space	Installed			

Not Required:			
Lifts	N/A		
External hard landscaping	Acceptable		

# The Bursary

The Bursary accommodation is located over three floors. A ramp is installed at the front entrance and a landing and steps at the rear; this was designed as a managed exit. An Entry phone system is installed at the front entrance. The entrance opens into a lobby and provides access to the ground floor. There are toilets on the ground and second floors and a disabled toilet on the ground. Disabled parking is provided across the road in the Schools car park.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
			1 - 3 Years	3 - Onwards	1-10
Work Required:					
Access to all floors above ground	Via stairs only, no wheelchair access	Install lift			8
Lifts	None	Install a lift		<b>✓</b>	8
Completed:					
Entrances and exits inc emergency use	Compliant				
Door entry system	Installed				

#### Audit 2022

Toilets and washing facilities	Installed		
External hard landscapes	Acceptable		
Visual fire alarm adaption	Completed		
	Designated car park space available opposite & dropped kerbs in place to car park		
Door Furniture	Access control installed		
Handrails	Completed		
Not Required: Furniture	N/A		

#### Classics

The classrooms are located within a grade 2\* listed building. All rooms are at first floor level except one, this is classroom 7 at ground level and is accessed from the old Quad. The main entrance provides access to a stair lobby leading to a first floor landing and access is gained directly to Lower Bench and Arnold Library. A secondary fire escape route via a spiral staircase is provided from Upper Bench. There are no toilet facilities in this area.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
			1 - 3 Years	3 - Onwards	1-10
Completed:					
Access to all floors above ground	No access available, stairs unsuitable	Classroom 7 on Ground floor is accessible			
Entrances & exits inc emergency use	Access/exit possible with assistance	Classroom 7 on Ground floor is accessible			

#### Audit 2022

External hard landscaping	Acceptable			
Furniture	- Compliant			_
Other	Parking available & signs installed			_
Not Required: Handrails	N/A	Grade 2 listed, adaptation not possible		
Lifts	None Available	No possibility of installing a lift		
Door furniture	Unsuitable	Grade 2 listed, adaptation not possible		
Door entry systems	Not required	N/A		
Toilets & wash facilities	Available in New Quad			
Door vision panels	None fitted	Grade 2 listed, adaptation not possible		

# **Collingwood Centre**

Former catholic School campus adjacent to the Close. It comprises of a range of single and multi story buildings roughly arranged around a central courtyard. There is a large multi-purpose sports hall and coffee shop. The main part of the complex is the gothic revival school building built over 3 floors. During the recent refurbishment project the majority of the site has been extensively improved and all of the disability access requirements have been met.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
			1 - 3 Years	3 - Onwards	1-10
Completed:					
Access to all floors above ground	Fully compliant				
Handrails	Fully compliant				
Lifts	Fully compliant				
Entrances and exits inc emergency use	Fully compliant				

#### Audit 2022

Door furniture	Fully compliant			
Door entry systems	Fully compliant			
Toilets & washing facilities	Fully compliant			
Signs	Fully compliant			
Induction loops	Fully compliant			
Visual fire alarm adaption	Fully compliant			
Furniture	Fully compliant			
Door Vision Panels	Fully compliant			
External hard landscaping Other	Fully compliant			

#### **Crescent House**

The accommodation is arranged over three levels which includes the basement. There are level changes on each floor which makes any adaption impossible The entrance is on the west side via a flight of external steps, this opens into a hallway and gives access to the first floor and the basement where there can be found two external sets of fire escape steps. Toilets are located on the ground floor. Parking is available at the front of the building. Building currently unoccupied.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
		·	1 - 3 Years	3 - Onwards	1-10
Work Required:					
Handrails	None compliant	Install new and modify existing		<b>~</b>	3
Lifts	None Available	Install a lift		<b>~</b>	9
Entrances & exits inc emergency use	Access/exit very difficult up steep steps	Very difficult to modify		<b>✓</b>	9
Door furniture	Unsuitable	Modify as appropriate		<b>~</b>	3
Door entry systems	None fitted	Install system		<b>~</b>	5

				_
Δ	udi	t 2	റാ	7

Audit 2022	1	1			i
Toilet & washing facilities	Not provided	Disabled provision not feasible			6
Visual Fire alarm adaption	None fitted	Will be fitted when fire alarm replaced			
Completed:					
Furniture	New - Compliant				
Door vision panels	Part compliant		-	_	_
Vision panels	Tare compliant				
Other	Designated parking space	Installed signage	_	_	_
Not Required/unachievable					
Access to all floors above ground	Via stairs only, no wheelchair access possible				
Induction loops	Mobile loop unit	N/A			
External Hard Landscaping	Acceptable	N/A			

# Geography

The accommodation is located over three floors. Access is from the forecourt off Barby Road and Horton Crescent. The access from Horton Crescent is stepped. The Entrance provides direct access to a stair lobby and ground floor classrooms. There is no disabled toilet provision due to lack of space

Possible limitations on Access	Summary of				Feasibility
	Audit	Adjustments	1-3	3- Onwards	1-10

Addit 2022				
Completed:	Via stairs only,			
Access to all floors above ground	no wheelchair			
	access			
	400033			
No. of the No.				
	Improvements			
	made			
Introduction loops	Mobile loop			
	unit actioned			
	dilit actioned			
External hard landscaping	Acceptable			
	Replaced			
	knobs with			
Door vision panels	compliant			
	handles			
	Hariares			
	Now Installed			
Parking	Now installed			
Not Required/ not possible to achieve				
Not nequired/ not possible to define ve				
Lift	None	Not		
	available	required, GF		
		classrooms		
		available		
Toilets & washing facilities				
	None	No space to		
	available	adapt		
		existing		
Entrances & exits inc emergency use	Level access			
	to Ground			
	to Ground			
	floor			
	floor classrooms			
	floor classrooms			
	floor			
	floor classrooms			

# History

The accommodation is located on three floors, organised in an L-shaped corridor. The stepped entrance is located off the forecourt to the Temple Reading room, on Barby road. The entrance provides direct access to a corridor that leads to an internal courtyard and three storey classroom areas. New ramp access installed 2014.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Priority for Action		Feasibility
	,		1 - 3 Years	3 - Onwards	1-10		
Completed:							
Toilets & washing facilities	Disabled Toilet on ground floor						
Entrances and exits inc emergency use	Ramp installed						
Door vision panels	Fitted						
Handrails	Non- compliant handrails replaced						
Other	Designated parking available	Sign installed					
Door Furniture	Replaced						
Furniture	Replaced 2015						
Door entry system	Installed 2020						

Not Required:				
Access to all floors above ground	Via stairs at present	N/A ground floor classrooms available		
External hard landscaping	Acceptable	N/A		

# I.T Department

Access is gained to classrooms from Horton Crescent. All entrances to the building are stepped. The classroom entrance provides access to a lobby and a small flight of steps to one classroom and a spiral staircase to the other two above on the first floor. Toilet provision is on the first floor above I.T support and is shared with Geography. There are no disabled toilets. Achieving compliance will be physically impossible given the building constraints

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority fo	Feasibility	
			1 - 3 Years	3 - Onwards	1-10
Work Required:					
Completed:					
Door vision panels	Installed				
Other	Designated parking	Signage installed			
Door Entry System	Installed				

Not Required/impossible to achieve				
Access to all floors above ground	Via stairs only, no wheelchair access			
Lifts	None available	No space to install lift		_
		Entrance level but only gets you to a small lobby everywhere stepped beyond the lobby		

# Learning Support

All classrooms are located on the first floor. Access is via the car park behind the SCR building of Horton Crescent. The entrance door leads to a stair lobby which provides access to all classrooms on the first floor. A secondary fire escape route is via one classroom, and the toilets by another.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
	,	,	1 - 3 Years	3 - Onwards	1-10
Work Required					
Entrances & exits inc emergency use	Accessed via stairs to first floor	Install handrail to external step,		•	3
Door entry systems	None available	Install system		•	5
Completed:					
Handrails	Addressed Dec 2013	Completed			
Door furniture	Addressed Dec 2013	Completed			
Visual fire alarm adaption	Addressed Dec 2013	Completed			
Door vision panels	Addressed Dec 2013	Completed			_
Other	Designated parking space in SCR car park	Installed			

I	Not Required / impossible to achieve				
	Access to all floors above ground level	Via stairs only, no wheelchair access	Not possible to install a lift		
			-		
	Lifts	Not feasible to install			
			_	_	
Į					

# **Macready Theatre**

The accommodation is located in a Grade 2 listed building. The arrangement of accommodation is complex and located over two floors. The foyer, dressing rooms and toilets are located on the ground floor, and the auditorium on the first. The two principle entrances are located on the side and front of the building accessed from either Lawrence Sheriff Street or Little Church Street and both have steps. The main stair leading to the auditorium also serves as a fire escape and has fire doors at an intermediate landing. Other fire escape stairs are also provided and open up onto steps in all locations, there are no ramps in these areas. A disabled toilet is available to the side of the foyer and limited car parking is available on the forecourt or at the rear of the building. Ramp installed 2017 to main entrance and lift from foyer to auditorium installed providing compliant access.

Possible limitations on Access	mitations on Access Summary of Audit Reasonable Adjustments	Reasonable Adjustments	Priority fo	Feasibility	
		1 - 3 Years	3 - Onwards	1-10	
Work Required					
Completed:					
Toilet and washing facilities	Disabled toilet on ground floor				
Induction loops	Mobile loop unit actioned				

#### Audit 2022

Visual fire alarm system	Completed			
Install Lift	Completed			
Install ramp	Ramp installed 2017			
Handrails	Completed			
Door Furniture	Completed			
Door Vision Panels	Completed			
Other	Designated parking space available	Signage installed		
Not Required: External hard landscaping	Acceptable			

#### Museum

The Burns museum is located in the former coach house between School Field House and the Science School on Barby Rd. Access is restricted to guided tours only. The accommodation is set on the ground floor only, the first floor and rear entrances have flush thresholds. The main entrance opens into the main gallery off of which two other rooms can be accessed. There are no internal doors and there is no provision for disabled toilets.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
		·	1 - 3 Years	3 - Onwards	1-10
Work Required:					
Door furniture	Unsuitable	Modify as appropriate			3

#### Audit 2022

Addit 2022			
	Designating parking available (located at the Book Shop)		
Not Required:			
Access to all floors above ground	N/A		
Handrails	N/A		
Lifts	N/A		
Entrances and exits inc emergency use	N/A		
Door entry systems	None fitted – always accompanied		
Toilets & washing facilities	N/A		
Door vision panels	N/A		
External hard landscaping	Acceptable		

#### **Music School**

The accommodation is located on three floors, arranged about a central stair. There are two entrances, the principal entrance accessed from Hillmorton Road leads directly to the reception area. The second entrance also links with the Temple Speech Room and is accessed from the car park on the western side of the building. There is a separate external fire escape from the New Music Room. Toilets are provided on the first and second floors, there are no disabled facilities in music but these are available in the adjoining TSR. There is limited space for parking at the side of the building. A lift has been installed

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action Summary of Audit Reasonable Adjustments		iority for Action Feasi	Feasibility
			1 - 3 Years	3 - Onwards	1-10	
Work Required:						
Door furniture	Unsuitable	Modify as appropriate	<b>✓</b>		4	

Audit 2022	1	•	•	i i	
Completed:					
Access to all floors above ground	Lift installed				
Lifts	Installed		-		
Entrances & exits inc emergency use	Access/exit possible with assistance	Rear entrance compliant	-	_	_
Toilets & washing facilities	Disabled facility on ground floor of TSR	Compliant	_	_	
Door vision panels	Compliant	Installed	-	_	
Door entry System	Installed				
Not Required:					

#### New Modern Languages

The accommodation is located on three floors, arranged around a central stair. The entrance is located on Horton Crescent. This entrance provides direct access to the main lobby and stairs and also the ground floor classrooms. The first floor is accessed via stairs and a lift which leads to the classrooms at this level and above. The toilets are located on the ground floor off of the lobby with disabled facilities.

Possible limitations on Access	Summary of Audit	Priority for Action Reasonable Adjustments		or Action	Feasibility
			1 - 3 Years	3 - Onwards	1-10
Completed: Access to all floors above ground	Fully compliant				

# Audit 2022

Handrails	Fully compliant		
Lifts	Fully compliant		
Entrances and exits inc emergency use	Fully compliant		
Door furniture	Fully compliant		
Door entry systems	Fully compliant		
Toilets & washing facilities	Fully compliant		
Signs	Fully compliant		
Induction loops	Fully compliant		
Visual fire alarm adaption	Fully compliant		
Furniture	Fully compliant		
Door Vision Panels	Fully compliant		
External hard landscaping Other	Fully compliant		

# New Quad

Accommodation is located in grade 2\* listed building. Classrooms are located at ground, first and second floor levels, via stairs only. A secondary fire escape route is provided. Toilets are located just off of the New Quad. Parking is available on the 'Porridge'.

Possible limitations on Access	ons on Access Summary of Audit Reasonable Adjustments	Summary of Audit	mitations on Access Summary of Audit Reasonable Adjustments	Priority for Action Summary of Audit Reasonable Adjustments		Priority for Action	
		·	1 - 3 Years	3 - Onwards	1-10		
Toilets & washing facilities	Provided	Modify to be fully compliant		<b>~</b>	6		

Λ.	. 4:1	20	2
Αι	ıdit	20	122

Completed:	Access/exit possible to Ground floor with			
Entrances & exits inc emergency use	assistance	mobile ramp provided		
Other	parking space	Installed signage		
Not Required: Access to all floors above ground	Via stairs only, no wheelchair access	Historic building – no adaption possible		
Access to all moors above ground	via stairs only, no wheelerian access	Thistoric building The adaption possible		
Handrails		Install new and modify existing - not feasible in		
		grade 2* listed building		
Door furniture	Unsuitable	No possible modification Grade 2 * listed		
Door entry systems	None available	Not possible grade 2* listed		
External hard landscaping	Acceptable	N/A		

# Old Modern Languages

The accommodation is located on two floors, arranged around a central stair. The entrance is located to the side of a forecourt off Barby Road. This entrance provides direct access to the main lobby and stairs and also the ground floor classrooms. The first floor is accessed via the stairs only which leads to the classrooms at this level. The toilets are located on the ground floor off of the lobby, however there are no disabled facilities. There is a fire escape stair externally from the first floor and car parking is available both in front and behind the building. **Building to be demolished, not a priority.** 

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
		7, 11	1 - 3 Years	3 - Onwards	1-10
To be demolished no works planned					

Addit 2022	1	i	i i	i	i
6: 61 1					

#### **Science Schools**

The accommodation is arranged in a complex layout over three floors. There are three entrances accessed from Barby Road, a fourth is accessed from the first floor level of the Arts and Design Centre. Two of these entrances are ramped. Toilets are located on the ground floor and in the basement. A disabled toilet is available on the ground floor. A lift, internal bridge links and ramps provide access to all levels. Limited parking is available at the front of the building.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
			1 - 3 Years	3 - Onwards	1-10
Work Required:					
Door furniture	Unsuitable	Modify as appropriate	<b>✓</b>		4

Λ	-11:4	00	00
Aυ	aıt	70	177

Tidalit ZOZZ	1	1			
Completed:					
Lifts	Main chair lift installed				
Toilets & washing facilities	Provided at ground level	-	<u>-</u>		
Other	Designated Parking space	-	-		
Door entry system	Installed				
Not Required:					
Access to all floors above ground	Lifts available				
	-	-	_	_	_

# Senior Common Room

The accommodation is located on two floors, the upper ground and basement area are linked by a central stair. There are four entrances, the two principle entrances are accessed from Horton Crescent. One of them through the car park. Both via multiple steps. The third entrance via a ramp and through Reprographics and the fourth down some steps to the basement bar area accessed from the side car park. Toilets are located on the ground floor.

Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
			1 - 3 Years	3 - Onwards	1-10
Work Required:					

#### Audit 2022

Entrances & exits inc emergency use	Access/exit heavily stepped to main entrances level access available via reprographics	Modify as appropriate		<b>~</b>	10
Door furniture	unsuitable	Modify as appropriate	<b>✓</b>		3
Door entry systems	None fitted	Install system		•	5
Toilets & washing facilites	On ground floor	Make disabled provision	<b>✓</b>		6
Induction loops	None available	Install where possible	•		2
Visual fire alarm adaption	None fitted	Will be fitted when fire alarm replaced.  Modify fire alarm to include beacons.			5
Completed: Other	Designated parking space	Installed			
Not Required: External hard landscaping	Acceptable				

# **Sports Centre**

The Sports Centre facility is located over two floors, level access can be used to reach all ground floor areas including the swimming pool, gym, external playing areas and the Fives Courts.

The first floor is accessible via a lift and leads to the offices and the cafe. There is no disabled access available to the viewing gallery and no adaption possible.

	Possible limitations on Access	Summary of Audit	Reasonable Adjustments	Priority for Action		Feasibility
	, , , , , , , , , , , , , , , , , , , ,		1 - 3 Years	3 - Onwards	1-10	
	Work Required:					
	Wet side disabled facilities	Disabled changing facilities required	In budget for 2023	<b>✓</b>		5

Building Access
Audit 2022

Addit 2022					
Completed:	Lift available but does not service viewing				
Access to all floors above ground	gallery				
Lifts	2 lifts installed				_
Entrances & exits inc emergency use	Access/exit possible without assistance	Compliant			
G ,	, '	·			
Door furniture	Compliant		-	-	-
Toilets & washing facilities	Installed				-
Visual fire alarm adaption	Completed		_		-
External hard landscaping	Acceptable		-	-	-
External nara fanascaping	ricceptuble				
Other	2 Designated parking spaces			-	-
Other	2 Designated parking spaces				
Door entry system	Installed				
200. 0 / 0/000	Instanca				
Not Required:					
Not Required.					